

# BODY FAIL TAG REPORT

(Failed material tags were first completed in May, 1996)

<b>Total Failed Materials Reported From May, 1996 to End Of:</b>
----------------------------------------------------------------------

Fail Tag Description	June 2006	May 2006	April 2006	March 2006	Feb 2006	Jan 2006	Dec 2005	Nov 2005	Oct 2005	Sept 2005
Battery Box	7	7	7	7	7	7	7	7	7	7
Body Mounts/Outriggers/ Clamps	5	5	5	5	5	5	5	5	5	5
Body Structure/Sheet Metal/ Rusting	2	2	2	2	2	2	2	2	2	2
Body Decals/Lettering/Paint	14	5	5	5	5	5	5	5	5	5
Crossing Arm	87	86	86	86	86	86	85	84	84	84
Dash	3	3	3	3	3	1	1	1	1	1
Defrosters/Defroster Motors	2	2	2	2	2	2	2	2	2	2
Dust Leaks	3	3	3	3	3	3	3	3	3	3
Emergency Exits	25	25	25	19	19	18	18	18	18	18
Electrical	7	7	7	7	5	3	1	1	1	1
Entrance Door – Vandalock/Seal/Alignment	11	11	11	17	15	12	12	10	10	10
Entrance Door – Air-Operated	7	7	7	5	4	1	1	--	--	--
Fire Extinguishers	1	1	1	1	1	1	1	1	1	1
Flooring	0	0	0	0	0	0	0	0	0	0
Glass	5	5	5	5	5	4	4	4	4	4
Heaters	15	15	15	15	15	15	15	15	15	15
Interior Headliner	1	1	1	1	1	1	1	1	1	1
Loading Lights	19	19	19	19	18	17	17	17	17	17
Mirrors	36	36	36	36	36	36	36	36	36	36
Mud Flaps	2	2	2	2	2	2	2	2	2	2
Radios/PA Systems/Speakers	5	5	5	4	4	4	4	4	4	4
Safety Equipment	1	1	1	1	1	1	1	1	1	1
Seats - Coverings/Seat Belts/Driver's Seat	9	9	9	9	9	8	8	8	8	8
Stop Arms – Electric	21	21	21	21	21	14	14	14	14	14
Stop Arms – Vacuum/Air	4	4	4	3	3	3	3	3	3	3
Strobe Lights	1	0	0	0	0	0	0	0	0	0
Roof Hatches	2	2	2	2	2	2	2	2	2	2
Tow Hooks/Rear Bumper	0	0	0	0	0	0	0	0	0	0
Wheelchair	7	7	7	7	7	7	7	5	5	5
Windshield Wipers/Washers	18	18	18	17	16	16	14	14	14	14